

(FILE 'HOME' ENTERED AT 15:32:30 ON 20 JUN 2005)

FILE 'USPATFULL, USPAT2' ENTERED AT 15:35:36 ON 20 JUN 2005

L1 1908 SEA ABB=ON PLU=ON 427/146000-152000/NCL
L2 92 SEA ABB=ON PLU=ON 427/146000-152000/NCL
TOTAL FOR ALL FILES
L3 2000 SEA ABB=ON PLU=ON 427/146000-152000/NCL
L4 390 SEA ABB=ON PLU=ON L1 AND SCREEN?
L5 31 SEA ABB=ON PLU=ON L2 AND SCREEN?
TOTAL FOR ALL FILES
L6 421 SEA ABB=ON PLU=ON L3 AND SCREEN?
L7 1 SEA ABB=ON PLU=ON L1 AND (BACKING FOIL?)
L8 0 SEA ABB=ON PLU=ON L2 AND (BACKING FOIL?)
TOTAL FOR ALL FILES
L9 1 SEA ABB=ON PLU=ON L3 AND (BACKING FOIL?)
D BIB AB
L10 236 SEA ABB=ON PLU=ON L1 AND (?SCREEN? (5A) ?PRINT?)
L11 21 SEA ABB=ON PLU=ON L2 AND (?SCREEN? (5A) ?PRINT?)
TOTAL FOR ALL FILES
L12 257 SEA ABB=ON PLU=ON L3 AND (?SCREEN? (5A) ?PRINT?)
L13 37 SEA ABB=ON PLU=ON L10 AND ((?THERMAL? OR HEAT? OR BAK?) (5A)
(CURE OR CURES OR CURED OR CURING OR CROSSLINK?))
L14 5 SEA ABB=ON PLU=ON L11 AND ((?THERMAL? OR HEAT? OR BAK?) (5A)
(CURE OR CURES OR CURED OR CURING OR CROSSLINK?))
TOTAL FOR ALL FILES
L15 42 SEA ABB=ON PLU=ON L12 AND ((?THERMAL? OR HEAT? OR BAK?) (5A)
(CURE OR CURES OR CURED OR CURING OR CROSSLINK?))
L16 42 FOCUS L15 1-
D 1-42 ALL IND RN
D L16 1-42 BIB AB
L17 1 SEA ABB=ON PLU=ON US3985602/PN
L18 0 SEA ABB=ON PLU=ON US3985602/PN
TOTAL FOR ALL FILES
L19 1 SEA ABB=ON PLU=ON US3985602/PN
L20 0 SEA ABB=ON PLU=ON L17 AND SCREEN?
L21 0 SEA ABB=ON PLU=ON L18 AND SCREEN?
TOTAL FOR ALL FILES
L22 0 SEA ABB=ON PLU=ON L19 AND SCREEN?
L23 0 SEA ABB=ON PLU=ON L17 AND MASK?
L24 0 SEA ABB=ON PLU=ON L18 AND MASK?
TOTAL FOR ALL FILES
L25 0 SEA ABB=ON PLU=ON L19 AND MASK?
L26 1 SEA ABB=ON PLU=ON US4078015/PN
L27 0 SEA ABB=ON PLU=ON US4078015/PN
TOTAL FOR ALL FILES
L28 1 SEA ABB=ON PLU=ON US4078015/PN
L29 0 SEA ABB=ON PLU=ON L26 AND MASK?
L30 0 SEA ABB=ON PLU=ON L27 AND MASK?
TOTAL FOR ALL FILES
L31 0 SEA ABB=ON PLU=ON L28 AND MASK?
L32 0 SEA ABB=ON PLU=ON L26 AND SCREEN?
L33 0 SEA ABB=ON PLU=ON L27 AND SCREEN?
TOTAL FOR ALL FILES
L34 0 SEA ABB=ON PLU=ON L28 AND SCREEN?
L35 2989 SEA ABB=ON PLU=ON 428/914000/NCL
L36 91 SEA ABB=ON PLU=ON 428/914000/NCL
TOTAL FOR ALL FILES
L37 3080 SEA ABB=ON PLU=ON 428/914000/NCL
L38 928 SEA ABB=ON PLU=ON L35 AND (SCREEN?)
L39 39 SEA ABB=ON PLU=ON L36 AND (SCREEN?)
TOTAL FOR ALL FILES

L40	967	SEA ABB=ON	PLU=ON	L37 AND (SCREEN?)	
L41	476	SEA ABB=ON	PLU=ON	L38 AND (?SCREEN? (5A) ?PRINT?)	
L42	33	SEA ABB=ON	PLU=ON	L39 AND (?SCREEN? (5A) ?PRINT?)	
TOTAL FOR ALL FILES					
L43	509	SEA ABB=ON	PLU=ON	L40 AND (?SCREEN? (5A) ?PRINT?)	
L44	116	SEA ABB=ON	PLU=ON	L41 AND ((?THERMAL? OR HEAT? OR BAK?) (5A) (CURE OR CURES OR CURED OR CURING OR CROSSLINK?))	
L45	5	SEA ABB=ON	PLU=ON	L42 AND ((?THERMAL? OR HEAT? OR BAK?) (5A) (CURE OR CURES OR CURED OR CURING OR CROSSLINK?))	
TOTAL FOR ALL FILES					
L46	121	SEA ABB=ON	PLU=ON	L43 AND ((?THERMAL? OR HEAT? OR BAK?) (5A) (CURE OR CURES OR CURED OR CURING OR CROSSLINK?))	
L47	102	SEA ABB=ON	PLU=ON	L44 AND (REMOV? OR PEEL?)	
L48	4	SEA ABB=ON	PLU=ON	L45 AND (REMOV? OR PEEL?)	
TOTAL FOR ALL FILES					
L49	106	SEA ABB=ON	PLU=ON	L46 AND (REMOV? OR PEEL?)	
L50	106	FOCUS	L49 1-		
	D 1-20 BIB AB				

⇒